



1. INTERNAL GUTTER
 2. CORRUGATED METAL ROOF PANELS
 3. STRUCTURAL MEMBER
 4. ROOF PANEL TRIMMED FLUSH AT GUTTER 'L' METAL INSTALLED WHEN
 5. PRO-TECH COATING (EC-100)
 6. INSTALL 'Z'COUNTERFLASHING IF POLYURETHANE AND PROTECTIVE COATING
CANNOT BE APPLIED UNDER SKYLIGHT FRAME
- NOTE: CURB MAY BE METAL (OPTIONAL, VENTS)

	METAL ROOF/INTERNAL GUTTER (DWG. 09)	DRAWN BY:	DATE:	APPROVED:
	3003 North 73rd Street, Scottsdale, AZ 85251 402 East Grand Road, Tuscon, AZ 85705	SCALE:	PROJECT NO:	DRAWING NO.