



1. INTERNAL GUTTER
2. CORRUGATED METAL ROOF PANELS
3. STRUCTURAL MEMBER
4. ROOF PANEL TRIMMED FLUSH AT GUTTER 'L' METAL INSTALLED WHEN
5. PRO-TECH COATING (EC-100)
6. INSTALL 'Z' COUNTERFLASHING IF POLYURETHANE AND PROTECTIVE COATING CANNOT BE APPLIED UNDER SKYLIGHT FRAME

NOTE: CURB MAY BE METAL (OPTIONAL, VENTS)



### METAL ROOF/INTERNAL GUTTER (dwg. 09)

3003 NORTH 73RD STREET, SCOTTSDALE, AZ 85251  
402 EAST GRAND ROAD, TUCSON, AZ 85705

DRAWN BY:

DRAWN BY:

APPROVED:

SCALE:

PROJECT NO:

DRAWING NO: