



- 1. EXTENDED PROTECTIVE COATING ON EXIST. ROOF
- 2. 5/8" PLYWOOD SCREW TO CURB
- 3. 20 GA. G.I. CURB COVER
- 4. MECHANICAL UNITE
- 5. TECH GUARD COATING SYSTEM
- 6. 2X2 BLOCKING
- 7. MECHANICAL CURB
- 8. NEW FOAM PATCH (TECH GUARD)
- 9. EXISTING PLYWOOD
- 10. SECURE CURB TO ROOF
- 11. EXIST. FOAM ROOF

	<b>REPAIR DETAIL (dwg. 39)</b>	DRAWN BY:	DRAWN BY:	APPROVED:
	3003 NORTH 73RD STREET, SCOTTSDALE, AZ 85251 402 EAST GRAND ROAD, TUCSON, AZ 85705	SCALE:	PROJECT NO:	DRAWING NO: